Fig. 1A






Fig. 1B




PRIOR ART




PRIOR ART

DOCKET NO.: 8017-1158
APPLN NO.: 10/522,156
REPLY TO NOTICE OF ALLOWABILITY OF: APRIL 25, 2008
REPLACEMENT SHEET

Fig. 3A










Fig. 3D



## PRIOR ART

DOCKET NO.: 8017-1158 APPLN NO.: 10/522,156 REPLY TO NOTICE OF ALLOWABILITY OF: APRIL 25, 2008 REPLACEMENT SHEET

Fig. 4A



PRIOR ART

148

Fig. 5






Fig. 6



Gate voltage

Fig. 7A






Fig. 8




Fig. 9A




Fig. 9B




Fig. 10

